

## Park spindle up



The PARK Z  +  function will move the spindle assembly to the absolute Z 0 position or all the way up.

### Activating Park Z.

Press the SHIFT  key and then the Z-AXIS JOG UP ARROW  to raise the spindle assembly to the absolute Z 0 position.

Keypad status bar displays:

“Parking ...”

Return to [the keypad overview](#).

Continue to [the table of contents](#).

From:

<https://manuals.cyborg-engravers.com/> - cyborg-engravers

Permanent link:

[https://manuals.cyborg-engravers.com/doku.php?id=de:x300:shift\\_raise\\_spindle\\_key](https://manuals.cyborg-engravers.com/doku.php?id=de:x300:shift_raise_spindle_key)

Last update: 2023/06/16 09:42

