

# Parkeer de spindel omhoog



The PARK Z  +  function will move the spindle assembly to the absolute Z 0 position or all the way up.

## Activating Park Z.

Press the SHIFT  key and then the Z-AXIS JOG UP ARROW  to raise the spindle assembly to the absolute Z 0 position.

Keypad status bar displays:

“Parking ...”

**Keer terug naar [het virtuele toetsenbord overzicht](#).**

**Ga verder naar [de inhoudstafel](#).**

From:

<https://manuals.cyborg-engravers.com/> - cyborg-engravers

Permanent link:

[https://manuals.cyborg-engravers.com/doku.php?id=nl:x200:shift\\_raise\\_spindle\\_key&rev=1741728609](https://manuals.cyborg-engravers.com/doku.php?id=nl:x200:shift_raise_spindle_key&rev=1741728609)

Last update: 2025/03/11 22:30

