Go home

CKGE_TMP_i Go Home
The “Go Home” hot key functions as a return to 0,0 soft home and tool lift key. Press the GO HOME hot key .
<font 10.0pt/inherit;;inherit;;inherit>Keypad status line display:
“Going Home ...”

From:
https://manuals.cyborg-engravers.com/ - **cyborg-engravers**

Permanent link:
https://manuals.cyborg-engravers.com/doku.php?id=en:x300:go_home_key&rev=1664052856

Last update: **2022/09/24 22:54**