Move spindle down 1 mm



Press the SHIFT key and then the Z-AXIS JOG DOWN ARROW to lower the spindle exactly 1 mm.
This key combination can be used several times one after the other. Each time the spindle will lower mm.

Return to the keypad overview.
Continue to the table of contents.

From:
https://manuals.cyborg-engravers.com/ - **cyborg-engravers**

Permanent link:
https://manuals.cyborg-engravers.com/doku.php?id=en:x300:shift_lower_spindle_key&rev=1664135561

Last update: **2022/09/25 21:52**