Park spindle up



The PARK Z  +  function will move the spindle assembly to the absolute Z 0 position or all the way up.

Activating Park Z. Press the SHIFT key and then the Z-AXIS JOG UP ARROW to raise the spindle assembly to the absolute Z 0 position. Keypad status bar display: “Parking …”

Return to the keypad overview.
Continue to the table of contents.

From:
https://manuals.cyborg-engravers.com/ - **cyborg-engravers**

Permanent link:
https://manuals.cyborg-engravers.com/doku.php?id=en:x300:shift_raise_spindle_key&rev=1664100788

Last update: **2022/09/25 12:13**