# Park spindle up



The PARK Z  +  function will move the spindle assembly to the absolute Z 0 position or all the way up.

**Activating Park Z.**

Press the SHIFT  key and then the Z-AXIS JOG UP ARROW  to raise the spindle assembly to the absolute Z 0 position.
Keypad status bar displays:
“Parking ...”

**Return to the keypad overview.**
**Continue to the table of contents.**

From:
https://manuals.cyborg-engravers.com/ - **cyborg-engravers**

Permanent link:
**https://manuals.cyborg-engravers.com/doku.php?id=en:x300:shift_raise_spindle_key&rev=1664100936**

Last update: **2022/09/25 12:15**