Verhoog de voedingssnelheid



Deze functietoets dient om de XY en Z voedingssnelheden te verhogen tot een maximum van 150%. Deze snelheid beïnvloedt de snelheid waarmee de machine in het materiaal graveert. Deze snelheid heeft geen invloed op de beweging tussen twee letters, dus boven het materiaal.
De voedingssnelheid wordt weergegeven op het virtuele controlepaneel als een percentage “%Feed” en als een reële snelheid in “mm/s (XY)”.
The feedrate override will determine the amount that the cut speed will be adjusted by.

When a file is being executed on the machine pressing the INCREASE CUT SPEED hot key will increase the feedrate in 1% increments.

Holding the INCREASE CUT SPEED hot key increases the feedrate at an increasingly faster rate.

Return to the keypad overview.
Continue to the table of contents.

From:
https://manuals.cyborg-engravers.com/ - **cyborg-engravers**

Permanent link:
https://manuals.cyborg-engravers.com/doku.php?id=nl:x200:increase_cut_speed_key&rev=1741725710

Last update: **2025/03/11 21:41**