

1.2 Component names and functions

Front view



1	spindle
2	cutter knob
3	graduated depth regulating nose
4	spring pressure ring
5	spindle motor
6	dust extraction hose
7	motor pulley
8	spindle pulley
9	dust extraction boot
10	nosecone for depth control

Rear view



1	Socket for power supply cable
2	On/Off switch (main switch)
3	Home setting of Y-axis motor
4	Ethernet socket
5	Socket for vacuum cleaner control
6	Nameplate X-200 with serial number

Virtual pendent


X200 Pendent
X
Y
Z
0.00
0.00
-10.81
jog speed
CYBORG
80.0 mm/s (XY)
0.0 mm/s (Z)
100 %
0 RPM
Please home machine
1x
10x
25x
DNC
1x
10x
25x
Z
Z
XYZ
TEST
coördinaten van de spindel positie
jog snelheid schaal
job snelheid informatie
start - pauze - vervolg
status- en commentaarveld
stofzuiger aan/uit
actuele thuis positie
uni- of bidirectioneel
verspanend graveren of diamant krassen
bewegingscontrole toetsen

Ga verder naar de installatie omgeving.
Ga verder naar de inhoudstafel.

From:
https://manuals.cyborg-engravers.com/ - **cyborg-engravers**

Permanent link:
https://manuals.cyborg-engravers.com/doku.php?id=en:x200:components&rev=1744893591

Last update: **2025/04/17 14:39**