Park spindle in the rear



The PARK Y  +  function will move the spindle assembly to the very rear of the engraving table.

Activating Park Z.

Press the SHIFT  key and then the Z-AXIS JOG UP ARROW  to raise the spindle assembly to the absolute Z 0 position.
Keypad status bar displays:
“Parking …”

Return to the keypad overview.
Continue to the table of contents.

From:
https://manuals.cyborg-engravers.com/ - **cyborg-engravers**

Permanent link:
https://manuals.cyborg-engravers.com/doku.php?id=en:x300:koppeling&rev=1664137834

Last update: **2022/09/25 22:30**