Cyborg X-300 Parts List

Part number	Description	Quantity
A31582	Spindle bearing	4
A31674	Spindle wave washer	3
https://manual.ketele.com/doku.php/intern/artikels/19327	Spindle shaft retaining ring (10 pcs)	1
A31660	plastic nosecone	1
A31783	vacuum exhaust pipe for engraving spindle	1
	circlips for nosecone	1
A31345	spindle motor (without plug, without timing pulley)	1
A31615	Z-axis stepper motor with leadscrew	1
A31614	X-axis / Y-axis stepper motor	2
A31463	flanged bearing for X / Y stepper motor	2
S30696	Idle pulley with 2 needle bearings, shaft and 2 circlips	3
18804	X-axis / Y-axis / Z-axis limit switch	3
18875	Z-axis inductive proximity switch	1
A31686	Safety cover inductive proximity switch	1
19695	safety cover flange bearing	2
A31233	Safety cover gas pressure spring cylinder	2
A31631	Igus X-axis e-chain element (this is just one element)	15
A31161	Igus Y-axis e-chain element (this is just one element)	23
A31632	Igus X-axis e-chain end elements (set)	1
A31160	Igus Y-axis e-chain end elements (set)	1
A31616	stepper motor drive for X-axis, Y-axis, Z-axis	3
A31346	drive for spindle motor	1
A31811	Meanwell 48 VDC power supply	1
A31069		
A31573		
A31447		
A31445		
A31445		
A31442		
A32653		

Part number	Description	Quantity
20174		
02447		
19228		
A31766		
18947		
18959		
A31464		
19891		
18928		
A31613		
A31676		
A31654		
A31655	index arrow support	1
A31673	hex screws M2 x 3 (10 pcs) for index arrow	2
18950	hex screws M2 x 4 (10 pcs) for index arrow support	2
S30695	cable with plug and wago contacts for vac / aux connexion	1
A31050	controller CNC-720	1

From:
https://manuals.cyborg-engravers.com/ - **cyborg-engravers**

Permanent link:
https://manuals.cyborg-engravers.com/doku.php?id=en:x300:parts_list&rev=1666101124

Last update: **2022/10/18 15:52**