De machine uitpakken en de inhoud van de doos controleren

Uitpakken

- Plaats de machine in de verpakking op de vloer, naast de tafel of het werkblad waarop ze geplaatst moet worden.
- Open de doos
- Neem de machine voorzichtig uit de doos en plaats ze op je werkblad. Laat je indien mogelijk helpen door een collega.
- Controleer de inhoud van de levering en gebruik daarvoor de controlelijst die je hieronder ziet.
- Maak wat plaats op je werkblad en leg daar alle geleverde accessoires.
- **Opgelet: Er zijn 2 personen!** nodig om de machine uit de doos te halen en op het werkblad te zetten.

After having unpacked, we advise you not to throw away the packing material. You might need it later when you need to move the machine to a new location or eventually, to ship the machine back to your vendor for service or repair.

Check the contents of the box


Image	Item description	Quantity	Checkbox
	Engraving machine Cyborg X-300	1	
	Cutter stand (cutters and knobs not included)	1	
	Cutter 3.175 mm x 125 mm, cutting width 0.2 mm	1	



Image	Item description	Quantity	Checkbox
	Cutter knob 3.175 mm	1	
	Vacuum hose 2 m	1	
	Wrench for cutter knob (2 mm)	1	
	Power Cord	1	
	CAT6A ethernet cable	1	
	USB stick with software and registration code for Pendent software and for Symmetry engraving software	1	
	Sticky mat 300 mm x 200 mm	1	

Image	Item description	Quantity	Checkbox
	Cable for vacuum or auxiliary output	1	

Continue to the X-300 cable connections.
Continue to the table of contents.

From:
https://manuals.cyborg-engravers.com/ - **cyborg-engravers**

Permanent link:
https://manuals.cyborg-engravers.com/doku.php?id=nl:x300:box_contents&rev=1669731876

Last update: **2022/11/29 15:24**