Wekelijks onderhoud

Periodic maintenance is of utmost importance to keep your machine in optimal working condition and to give it a long lifecycle.
When performing periodic maintenance, try to follow the prescriptions which follow hereunder.
It may be a good idea to write down your maintenance activities in a table.

• Verify the brass cutter knobs around the cutters. They must have an undamaged clean thread. Only use cutter knobs supplied by your dealer, and specifically made for the Cyborg X-300.
• Verify that the machine is always standing on a stable table or support, with sufficient space around it.

Continue to monthly maintenance.
Continue to the table of contents.

From:
https://manuals.cyborg-engravers.com/ - **cyborg-engravers**

Permanent link:
https://manuals.cyborg-engravers.com/doku.php?id=nl:x300:weekly&rev=1670251342

Last update: **2022/12/05 15:42**