

Symmetry Hotkeys

Function Keys¹⁾	
[F1]	Help Contents
[F2]	Edit Line by Centers
[F4]	Manual Edit
[F5]	Autoplate
[F6]	Quick Text Edit
[Shift] + Function Keys	
[Shift + F9]	Engrave Output
[Alt] + Character	
[Alt + A]	About
[Alt + B]	Borders
[Alt + D]	Object Fill and Tool Dimension
[Alt + M]	Multiplate
[Alt + S]	Serialize
[Alt + C]	Columnize

¹⁾

Please note that on many laptops, the [F1] through [F10] or [F12] function keys have other designated uses, such as turning up or down the volume. In order to use these function keys for their “original” purpose, there is a **[Fn]** key which has to be pressed before using the desired function key. This [Fn] key is to be found to the right of your space bar.

From:
<https://manuals.cyborg-engravers.com/> - **cyborg-engravers**

Permanent link:
https://manuals.cyborg-engravers.com/doku.php?id=de:symmetry:function_keys

Last update: **2023/06/16 09:42**

