

Weekly maintenance

Periodic maintenance is of utmost importance to keep your machine in optimal working condition and to give it a long lifecycle.

When performing periodic maintenance, try to follow the prescriptions which follow hereunder. It may be a good idea to write down your maintenance activities in a table.

- Verify the brass cutter knobs around the cutters. They must have an undamaged clean thread. Only use cutter knobs supplied by your dealer, and specifically made for the Cyborg X-300.
- Verify that the machine is always standing on a stable table or support, with sufficient space around it.

Continue to [monthly maintenance](#).

Continue to [the table of contents](#).

From:

<https://manuals.cyborg-engravers.com/> - **cyborg-engravers**

Permanent link:

<https://manuals.cyborg-engravers.com/doku.php?id=de:x300:weekly>

Last update: **2023/06/16 09:42**

