

# Weekly maintenance

---

Periodic maintenance is of utmost importance to keep your machine in optimal working condition and to give it a long lifecycle.

When performing periodic maintenance, try to follow the prescriptions which follow hereunder.

It may be a good idea to write down your maintenance activities in a table.

- Verify the brass cutter knobs around the cutters. They must have an undamaged clean thread. Only use cutter knobs supplied by your dealer, and specifically made for the Cyborg X-300.
- Verify that the machine is always standing on a stable table or support, with sufficient space around it.

**Continue to [monthly maintenance](#).**

**Continue to [the table of contents](#).**

From:

<https://manuals.cyborg-engravers.com/> - **cyborg-engravers**

Permanent link:

<https://manuals.cyborg-engravers.com/doku.php?id=en:x300:weekly>

Last update: **2023/10/20 12:16**

